State of Utah Department of Administrative Services Division of Facilities Construction & Management 4110 State Office Building WEBER STATE UNIVERSITY Fax: (801) 538 - 3267 Internet: http://www.dfcm.state.ut.us SCIENCE LAB BUILDING CURTAIN WALL REPAIR CREATED BY: P+A architects P+A architects
821 East Kensington Ave. OGDEN, UTAH Salt Lake City, Utah 84105 P: 801.484.1161 F: 801.485.4640 e-mail parchitects@comcast.net DFCM PROJECT NO. 07052810 **BUILDING NAME:** WEBER STATE UNIVERSITY SCIENCE LAB BUILDING NORTH & SOUTH CURTAIN WALL REPAIR OGDEN, UTAH PROJECT TITLE: SCIENCE LAB BUILDING **NORTH & SOUTH CURTAIN** WALL REPAIR WEBER STATE UNIVERSITY OGDEN, UTAH State of Utah— Department of Administrative Services ISSUE DATE: 02nd July, 2007 DFCM PROJECT NO: 07052810 DIVISION OF FACILITIES CONSTRUCTION CAD PROJECT NO: CAD DWG FILE: BRIAN AND SCOTT AND MANAGEMENT SCOTT COPYRIGHT: STATE OF UTAH SHEET TITLE 4110 State Office Building / Salt Lake City, Utah 84114 / 538-3018 **COVER SHEET** June 18th, 2007 SHEET NUMBER A-G1000 SHEET OF 6

## WEBER STATE UNIVERSITY SCIENCE LAB BUILDING CURTAIN WALL REPAIR

State of Utah

Department of Administrative Services

Salt Lake City, Utah 84114

Internet: http://www.dfcm.state.ut.us

CREATED BY: P+A architects

P+A architects
821 East Kensington Ave.
Salt Lake City, Utah 84105

e-mail parchitects@comcast.net

P: 801.484.1161 F: 801.485.4640

Division of Facilities

Construction & Management 4110 State Office Building

Phone: (801) 538 - 3018 Fax: (801) 538 - 3267

University

OGDEN, UTAH

## DFCM PROJECT NO. 07052810









